


















Projector Mount Installation Instruction

PM SERIES

<p>(A)</p>  <p>M4*8 10PCS</p>	<p>(B)</p>  <p>M5*9 7PCS</p>	<p>(C)</p>  <p>2PCS</p>	<p>(D)</p>  <p>P.W5.2*12*1 4PCS</p>	<p>(E)</p>  <p>Φ4*Φ7*37.5 4PCS</p>	<p>(F)</p>  <p>Φ4*50 4PCS</p>	<p>(G)</p>  <p>M3*8 4PCS</p>	<p>(H)</p>  <p>P.W3.2*10*1 4PCS</p>
<p>(I)</p>  <p>1PCS</p>	<p>(J)</p>  <p>1PCS</p>		<p>(K)</p>  <p>1PCS</p>				
<p>(L)</p>  <p>1PCS</p>	<p>Step:1</p>  <p>Diagram showing the assembly of the rail (L) with brackets (I, J, K) and screws (A, B, E, F, G, H). Labels include: (I) X1, (B) X4, (L) X1, (B) X1, (A) X4, (K) X1, (J) X1, and (A) X2.</p>		<p>Step:2</p>  <p>Diagram showing the final assembly step with screws (E, D, F) being inserted into the rail assembly. Labels include: (E) X4, (D) X4, and (F) X4.</p>				
<p>(M)</p>  <p>S=3mm 1PCS</p>	<p>(N)</p>  <p>S=4mm 1PCS</p>		<p>(O)</p>  <p>S=2.5mm 1PCS</p>				